

QUESTIONS & ANSWERS

Kill your exam at first Attempt



HP3-C32 Dumps
HP3-C32 Braindumps
HP3-C32 Real Questions
HP3-C32 Practice Test
HP3-C32 dumps free



HP

HP3-C32

HP Color LaserJet Enterprise(R) CP4020/CP4520 Series Printer

<http://killexams.com/pass4sure/exam-detail/HP3-C32>



Answer: C

QUESTION: 25

What must be done with an inter-connect board (ICB) that has been removed from a device?

- A. Reinstall the ICB in the same device or destroy the ICB.
- B. Install the ICB in another engine only for troubleshooting purposes.
- C. Ship the ICB back to HP to be refurbished.
- D. Service the ICB with a computer and USB port before reinstalling it.

Answer: A

Explanation:

I don't think this is a correct question because it is asking something that is not mentioned in any service repair manual. I am not sure about this question.

QUESTION: 26

What is the service strategy for the HP Color LaserJet Enterprise CM4540 MFP 3-bin Stapling Mailbox?

- A. The 3-bin Stapling Mailbox contains component-level repair parts for the life of the product and does not contain any Customer Self Repair parts.
- B. The 3-bin Stapling Mailbox is a field-replaceable unit, which also contains the front door and staple cartridge as Customer Self Repair parts.
- C. The 3-bin Stapling Mailbox is considered a Customer Self Repair part while the product is in warranty. Once the product is beyond warranty, component-level repair parts are available.
- D. The 3-bin Stapling Mailbox should last the life of the product and is not considered a replaceable unit. HP will only replace the mailbox if the stapling mechanism fails.

Answer: A

QUESTION: 27

When the alienation motor is installed correctly, in which position should the alienation motor PCA be?

- A. on top
- B. to the left
- C. to the right
- D. on bottom

Answer: A

QUESTION: 28

What is the main caution to remember when removing the HP Color LaserJet Enterprise CM4540 MFP scanner?

- A. The scanner must be removed with the SCB attached to prevent damage to the SCB cables.
- B. The top cover is not secured by screws, so you must be careful that the scanner does not fall off the back of the device.
- C. When removing the scanner, you only remove the scissor hinges from the bottom portions that attach to the engine.
- D. The control-panel adaptor must be removed with the scanner, requiring the USB cable to be routed through the scanner assembly.

Answer: C

QUESTION: 29

When the toner collection unit (TCU) must be removed to perform service on a device, which precautionary measure should field technicians remember to implement?

- A. Do not tip the TCU on its side after removing it from the device.
- B. Power off the device before removing the TCU.
- C. Retract the PGC mechanisms before removing the TCU.
- D. Close the ITB cleaning mechanism shutter after removing the TCU.

Answer: B

QUESTION: 30

Which action should you take directly after removing any print cartridges from the device?

- A. Check the level of toner in the toner collection unit.
- B. Cover the OPC (image drum) to protect it from excess light.
- C. Rest the cartridge upside down to avoid toner leakage.
- D. Use a finger to slide the Protective Glass Cleaner (PGC) over the scanner glass.

Answer: A



KILL EXAMS

KILLEXAMS.COM

For More exams visit <https://killexams.com/vendors-exam-list>



Kill your exam at First Attempt....Guaranteed!